

3. Loosen the Screw 1 for 2~3 turns counter clockwise.
Then loosen the Screw 2 & 3 for 1 turn counter clockwise.



4. Hammer the Screw 1, 2 & 3 slightly via another screw driver or smaller hammer as right picture.



5. Start to tighten the screws to reduce the backlash. During the adjustment, always drive the motor east / west via the manual button to make sure the Motor runs smoothly (or the power consumption is less than 300mA w/ antenna & w/o LNB) after fine-adjustment on the screws as step 6.

6. Tighten the Screw 1 clockwise for 1~2 turns. Tighten the Screw 2 & 3 for $\frac{3}{4}$ turns. Check if the backlash is improved by pushing the antenna by hand.

7. Repeat Step 6 but with less turns until the backlash is improved. Make sure the screws are not tighten too much via the power consumption or motor noise.

8. If the above does help, try once again from Step 3. If it doesn't work again, contact the vender.

p.s. The picture at right is the normal condition for the adjustment mechanism inside the motor.

